

Historic Preservation Commission

May 9, 2019

Action Item

Election of HPC Officers



Demolition Review

2515 1st Ave SW



Project Description

- Structure for demolition 20' x 25' City-owned barn
- Built in 1920
- Has not been surveyed
- City would like to demolish this structure to use the land for stormwater management





2515 1st Ave SW





2515 1st Ave SW

- Poor candidate for local land marking
- No evidence of historic significance
- Staff recommends immediate release

Demolition Review

412 2nd St SW



Project Description

- Structure for demolition is a singlefamily house
- Built in 1905
- Surveyed as eligible as part of a historic district
 - Architectural
 Reconnaissance Survey
 for Kingston in Cedar
 Rapids (2009)





412 2nd St SW





412 2nd St SW

- Not individually eligible
- Adjacent properties have already been approved for demolition
- Staff recommends release



Certificate of Appropriateness

1738 3rd Ave. SE



Project Description

- Primary structure constructed in 1920
- The applicant's request is to replace two wood windows with vinyl
 - The first floor windows on the west side adjacent to fire place
- Contributes to the 2nd
 & 3rd Ave District, but is not individually eligible





View of west facade





View of east facade





Historic Preservation Guidelines - Windows

APPROPRIATE:



- Retain and repair historic window sashes, exterior cap moldings, sills and frames
- Windows should be repaired rather than replaced. If non-original or beyond repair and replacement is necessary, the replacement should be in-kind to match the original in material and design.
- Replace windows with the home's original window material (e.g. wood for wood)
- Replacement windows should match the originals as closely as possible
- · Repair or install new storm windows
- Vinyl or aluminum products may be allowed at the rear of a house
- Windows should be preserved in their original location, size, and design and with their original materials and glass pattern.
- Windows may have screens and/or storm windows. See Screen, Storm and Security Windows Section, on page 32.

NOT APPROPRIATE:



- Windows constructed of modern building materials, such as vinyl or aluminum on the front and sides of homes
- · Decreasing the size of the window opening
- Altering window openings on front facades or side facades visible from the street to accommodate new windows of different size, proportion or configuration.
- Adding window openings that are not original to front facades or elevations visible from the street.
- Altering character defining window openings on all facades.
- New windows on front facades and sides visible from the street with snap-in or flush muntins.
- Enclosing or concealing basement windows on the exterior.



Impact of Design Guidelines is affected by the Location of a Building



If compromises must be made for budget reasons, priority should be given to exteriors that can be seen from the street and have the most impact on the streetscape. For example, retaining a front porch would have higher priority than keeping a back porch or than retaining wood siding on a rear elevation.

The figure above illustrates which elevations are considered front, rear, and side. As shown, any elevation that faces a public street or the intersection between a public street and an alley is considered a front elevation. An elevation that faces an adjacent primary structure is considered a side elevation. An elevation that faces only an alley or accessory building and cannot be seen from the public right of way is considered a rear elevation.



Criteria for Decision

- If any defining features of the building or structure as indicated, but not limited to those included on the Site Inventory Form(s) are proposed to be modified as a result of the proposal indicated on the application for Certificate.
- If the proposal is consistent with the Guidelines for Cedar Rapids Historic Districts and/or the most recent edition of the Secretary of Interior's Standards for Rehabilitating Historic Buildings.
- If the proposal mitigates adverse effects on the aesthetic, historic, or architectural significance of either the building or structure or of the local historic district or local historic landmark.



Recommendation

 City Staff recommends approval of installation of vinyl windows because it is less visible from the public right-of-way and other windows on the east side of the house have been replaced with vinyl.

Actions

- Approve as submitted; or
- Approve with modifications agreeable to the applicant; or
- Deny the application; or
- Request additional information.



5909 6th St SW Hold expires 6/4/19





Discussion

Proactive Preservation



Historic Preservation Commission

Staff Liaison:

Adam Lindenlaub

Comm. Dev. Planner
a.lindenlaub@cedar-rapids.org
319.286.5064

